

# TECHNICAL INFORMATION




63132

**Subject** ▶ Change of Ball Bearing

**For Models** ▶ 5017RKB

**Country** ▶ European countries, Algeria, Reunion

**Description** ▶ For quick repairing, the Ball Bearing in the gear chamber of Blade Case Complete has been changed from 608DDW (double sealed type) to 608 (seal-less type).  
(It is difficult to put a double sealed ball bearing in the gear chamber when there is much grease inside the gear chamber.)



|                             | ▶ <b>Current</b>                     | ▶ <b>New</b>                     |
|-----------------------------|--------------------------------------|----------------------------------|
| Cat. No.<br>of Ball Bearing | 608DDW<br>(With seals on both sides) | 608<br>(No seals on either side) |
| Part No.                    | 210005-4                             | 211034-0                         |

## Interchangeability(I/C)

| Item No. | Current part                    |  | Q'ty | I/C | New part                     |  | Q'ty | Note |
|----------|---------------------------------|--|------|-----|------------------------------|--|------|------|
| 015      | Ball Bearing 608DDW<br>210005-4 |  | 1    | Yes | Ball Bearing 608<br>211034-0 |  | 1    |      |

## Implementation

From Serial No. 1341G (Apr., 2001)