


- Subject** ▶ Change of Inner Flange 40
- For Models** ▶ 5007B, 5007NB, 5007NBA, 5007NH, 5007S, 5026D, 5036D, 5046D, 5057KB, 5611D, 5620D, 5621D, 5621RD, 5630D, 5820, BLS712, BSS730, LS0711B, LS0713, LS0713F, LS711D, M513, M514, M517
- Country** ▶ All countries except Canada, U.S.A., Chile, Mexico, Panama, and European countries.
Note: This technical information applies to the products using Inner flange 40 of 20mm(13/16") arbor.
- Description** ▶ Inner flange 40 has been changed as illustrated below.



Interchangeability(I/C)

| Item No. | Current part | | Q'ty | I/C | New part | | Q'ty | Note |
|------------|-----------------------------|--|------|-----|-----------------------------|--|------|------|
| See below. | Inner Flange 40 224199-9 | | 1 | ← | Inner Flange 40 224397-5 | | 1 | |

Interchangeability mark ;

The arrow ← means that the new part is substituted for the current.

Item No. of Inner flange 40

| | | | | | | | | | | | |
|--------|--------|---------|--------|--------|---------|--------|---------|--------|-------|-------|-------|
| 5007B | 5007NB | 5007NBA | 5007NH | 5007S | 5026D | 5036D | 5046D | 5057KB | 5611D | 5620D | 5621D |
| 023 | 024 | | 003 | 023 | 051 | | | 053 | 001 | 003 | 044 |
| 5621RD | 5630D | 5820 | BLS712 | BSS730 | LS0711B | LS0713 | LS0713F | LS711D | M513 | M514 | M517 |
| 041 | 044 | 019 | 056 | 003 | 006 | | | 056 | 023 | | 019 |

Implementation

5007NB: From Jun., 2003 production.
 BLS712, BSS730, LS0711B, LS0713, LS0713F, LS711D: From Oct., 2003 production.
 5007NBA, 5621RD: From Oct., 2003 production or later.
 5007B: Discontinued since Oct., 1993.
 5611D: Discontinued since May, 1995.
 5820: Discontinued since May, 1999.
 M513, M514: Discontinued since Jun., 1991.
 M517: Discontinued since Apr., 1993.
 5007NH, 5007S, 5026D, 5036D, 5046D, 5057KB, 5620D, 5621D, 5630D: To be informed later.