




# T ECHNICAL INFORMATION

- Subject** ▶ Change of Bumper
- For Models** ▶ 6905H
- Country** ▶ All countries
- Description** ▶ As illustrated below, Bumper has been changed for standardization.  
The new Bumper is identical with that of Model SI100.

▶ Current	▶ New
Bumper (Part No.421375-8)	Bumper (Part No.421747-7)
View from the Motor Housing side	View from the Motor Housing side
	 <p style="text-align: center;">Four bosses have been added on the inner surface of Bumper.</p>

**How to set the new Bumper in place:**

Aligning the projection on Bumper with the joint of Motor Housings (R) and (L) as illustrated on right, push Bumper until its inner bosses are securely put in the tapped holes of Motor Housing.



**Interchangeability(I/C)**

Item No.	Current part	Q'ty	I/C	New part	Q'ty	Note
020	Bumper 421375-8	1	Yes	Bumper 421747-7	1	

**Implementation**

From serial No.93305E (Mar.,2000)