


**Subject** ▶ Change of Hammer, Armature, etc.

**For Models** ▶ 6932FD

**Country** ▶ All countries

**Description** ▶ The following changes and addition have been implemented to increase power and to comply with UL standard.

1. Hammer has been changed.
2. The number of winding armature coil has been changed from 13 to 12.
3. Leaf spring has been added as illustrated below.



4. Holder cap has been changed. (For U.S.A. only)

## Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
022	Hammer 323996-1		1	No	Hammer 324404-5		1	Interchangeable as a set
045					Leaf Spring 232218-7		1	
036	Armature 619132-8		1	No	Armature 619140-9		1	
039	Holder Cap 643933-2		2	←	Holder Cap 643982-9		2	For U.S.A. only

### Interchangeability mark ;

The arrow ← means that the new part can be substituted for the current.

### Note

6932FD for U.S.A., Canada and Mexico is manufactured at MCA.

6932FD for all countries except U.S.A., Canada and Mexico is manufactured at MKC.

### Implementation

Immediately upon completion of preparation