





Subject ▶ Change of Field Assembly and Motor Housing Complete

For Models ▶ 9015B, 9015DB, 9016B, 9016DB

Country ▶ All countries

Description ▶ See below.

1. Field Assembly has been replaced by new one with thinner lead wires. However, the part No. of Field Assembly remains unchanged.
2. Holders of Motor Housing Complete have been modified as illustrated below so that the thinner lead wires can be held more firmly with them.

▶ Current	▶ New
<p style="text-align: center;">Diameter of Lead Wire : 2.89mm (1/8")</p>  <p style="text-align: center;">Field Assembly</p>	<p style="text-align: center;">Diameter of Lead Wire : 2.05mm (1/16")</p>  <p style="text-align: center;">Field Assembly</p>
 <p style="text-align: center;">Motor Housing Complete (Part No. 159996-3)</p>	 <p style="text-align: center;">Motor Housing (Part No. 183159-9)</p>

Interchangeability(I/C)

Item No.	Current part	Q'ty	I/C	New part	Q'ty	Note
018	Motor Housing Complete 159996-3	1	Yes	Motor Housing 183159-9	1	

Implementation

- 9015B : From serial No.83651E (Apr.,2000)
- 9015DB : From serial No.13819E (Apr.,2000)
- 9016B : From serial No.19251E (Apr.,2000)
- 9016DB : From serial No.5682E (Apr.,2000)