





T ECHNICAL INFORMATION



57432

- Subject** ▶ Changes on Gear Housing Complete and Screw
- For Models** ▶ 9060L, 9067, 9067L, 9067S, 9069, 9069S
- Country** ▶ All countries
- Description** ▶ As illustrated below, Gear Housing Complete and Screw have been changed for quick repair.

	▶ Current	▶ New
Gear Housing Complete	<p>Inscription of "3170064"</p>  <p>Hole</p> <p>(Part No.150968-1)</p>	<p>Inscription of "3172414"</p>  <p>Treatment for Screw M5</p> <p>(Part No.151631-9)</p>
Screw (4pcs.)	 <p>Tapping Screw (Part No.266027-2)</p>	 <p>Pan Head Screw w/spring washer (Part No.911226-8)</p>

Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
9060L: 038 9067/9067L/ 9067S/9069/ 9069S: 042	Gear housing complete 150968-1		1	No	Gear housing complete 151631-9		1	Interchangeable as a set
9060L: 030 9067/9067L/ 9067S/9069/ 9069S: 034	Tapping screw bind CT 5x16 266027-2		4	No	Pan head screw M5x18 911226-8		4	

Note

These changes are implemented exclusively on machines manufactured in Japan.

Implementation

9060L : No. 2245E Since January, 1999
 9067 : No. 15931E Since January, 1999
 9067L : No. 5399E* Since January, 1999
 9067S : No. Since January, 1999
 9069 : No. 86234E Since January, 1999
 9069S : No. 16232E Since January, 1999

* No.5691E~5790E: Old items