


TECHNICAL INFORMATION



74499

October, 2005

- Subject** ▶ Change of Safety Cover, Cap 20, Lock Lever and Blade Case Complete
- For Models** ▶ See below.
- Country** ▶ All countries
- Description** ▶ For complying with the European standards;
- 1) Safety cover has been modified. The new type Safety cover for Canada, USA and Mexico differs from the new one for the other countries.
 - 2) Cap 20 of rubber has been replaced by Cap of plastic. This modification applies to the model BLS820 for all countries except Canada, USA and Mexico.
 - 3) Lock lever of the models BLS820 and LS800D has been modified for Austria, France, Germany, Italy, Netherlands, Russia, Spain, Sweden, Switzerland, Algeria, Reunion, South Africa and China.
 - 4) At the same time on the modification of 3), Blade case or Blade case complete has also been modified for several countries.
- See illustration below for the added portions.



Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
199	Safety Cover 416908-2		1	Yes	Safety Cover 419481-1		1	LS0813, LS0813F, LS0811 and LS800D for all countries.
064	Safety Cover 416908-2		1	←	Safety Cover 419435-8		1	BLS820 for Canada, USA and Mexico
113	Cap 20 286212-1		5	←	Cap 416972-3		5	BLS820 except Canada, USA and Mexico
E05	Lock Lever 344807-7		1	←	Lock Lever 345710-5		1	BLS820 and LS800D for Austria, France, Germany, Italy, Netherlands, Russia, Spain, Sweden, Switzerland, UK, Algeria, Reunion, South Africa, China
039	Blade Case 183097-5		1	←	Blade Case 188079-2		1	BLS820 and LS800D for Bhutan, Hong Kong, Australia, New Zealand, Tahiti
039	Blade Case Complete 151904-0		1	←	Blade Case Complete 154940-5		1	BLS820 and LS800D for USA
039	Blade Case Complete 151905-8		1	←	Blade Case Complete 154941-3		1	BLS820 and LS800D for Canada
039	Blade Case Complete 152720-3		1	←	Blade Case Complete 154942-1		1	BLS820 and LS800D for Mexico

Interchangeability mark ;

The arrow ← means that the new part can be substituted for the current.

Implementation

BLS820: From November 2005 production.

LS0813, LS0813F: To be implemented in the middle of October 2005 production

LS0811, Discontinued since January, 2003

LS800D: Discontinued since July, 2003