

TECHNICAL INFORMATION



72144

- Subject** ▶ Change of Pin 5 and Lubricant
- For Models** ▶ 6952, 6953, BTD150, BTW150, BTW151
- Country** ▶ All countries
- Description** ▶ Pin 5 and its lubrication have been changed as described below.

	► Current	► New
Pin 5	1) Treated with disulfide of molybdenum and covered with rust preventing oil. 2) Its part No. is 268070-7.	1) Covered with Seal lubricant No.101 (Pt. No. 042010-1A: 100 g/1 set) 2) Its part No. is 256253-1.
Lubricant	Molybdenum Grease (Pt. No. 042019-3A: 500 g/1 set)	It is OK to lubricate the new pin 5 (256253-1) with Molybdenum grease instead of Seal lubricant No.101 for repair purpose.

Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
See below.	Pin 5 268070-7		2	Yes	Pin 5 256253-1		2	

Item No. of Pin 5

Model No.	6952	6953	BTD150	BTW150	BTW151
Item No.	026			028	

Implementation

6952: From serial No. 4545E (November, 2004)

The remaining models: As soon as the current parts in stock run out