

# TECHNICAL INFORMATION



89919  
August 2010

**Subject** ▶ Change of Controller

**For Models** ▶ AG3628, BUB360

**Country** ▶ All countries

**Description** ▶ Auto-stop may possibly result from 70 seconds continuous use of the models with the current controller selected to LOW mode.  
Therefore, the controller has been changed to prevent the possibility.  
**Note:** The battery protection against overdischarging in the current models will work properly without damaging the battery itself even if the above situation happens.

## Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
007	Controller 631975-8		1	←	Controller 620050-5		1	

### Interchangeability mark;

The arrow ← means that the new part can be substituted for the current.

## Implementation

From August 2010 production