

TECHNICAL INFORMATION




A5303
August 2014

Subject ▶ Elimination of Oil pump set



For Models ▶ DOLMAR: ES-164 TLC, ES-174 TLC, ES-2131 TLC, ES-2136, ES-2136 TLC, ES-2141, ES-2141 TLC, ES-34 TLC, ES-39 TLC, ES-43 TLC, AS-3726, AS-3731
Makita: DUC252, DUC302, UC3041A, UC3050A, UC3051A, UC3541A, UC3550A, UC3550AP, UC3551A, UC4041A, UC4050A, UC4051A, UC4550A, UC4551A, XCU02

Country ▶ All countries

Description ▶ Oil pump set has been eliminated.
Oil pump complete and Worm gear are the alternatives as shown below.



Oil pump set
(196419-0)



Oil pump complete
(142156-4)



Worm gear
(221427-3)

Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
See Note.	Oil pump set ----- 196419-0		1	←	Oil pump complete ----- 142156-4		1	046: AS-3726, AS-3731, DUC252, DUC302, XCU02 049: ES-164 TLC, ES-174 TLC, ES-2131 TLC, ES-2136, ES-2136 TLC, ES-2141, ES-2141 TLC, UC3050A, UC3051A, UC3550A, UC3550AP, UC3551A, UC4050A, UC4051A, UC4550A, UC4551A 075: ES-34 TLC, ES-39 TLC, ES-43 TLC, UC3041A, UC3541A, UC4041A

Interchangeability mark;

The arrow ← means that the new part can be substituted for the current.