





T ECHNICAL INFORMATION



75309
February 2006

- Subject** ▶ Change of Pin Cap and Shoulder Pin 5
- For Models** ▶ GA7020, GA7020S, GA9020, GA9020S, MT900, MT901, M907, M908, SA7021
- Country** ▶ All countries
- Description** ▶ Pin cap and Shoulder pin 5 have been changed again as illustrated below. Consequently, our previous technical information No.75224 expired last year in MKC and last month in MJ.

	▶ Current	▶ New
Pin Cap	 (416449-8)	 (419133-4)
Shoulder Pin 5	 (256499-9)	 (256491-5)

Interchangeability(I/C)

Item No.	Current part	Q'ty	I/C	New part	Q'ty	Note
001	Pin Cap 416449-8	1	No	Pin Cap 419133-4	1	Interchangeable as a set
GA7020, GA7020S, GA9020, GA9020S, SA7021: 035 MT900, MT901, M907, M908: 032	Shoulder Pin 5 256499-9	1	No	Shoulder Pin 5 256491-5	1	

Implementation

- GA7020, GA7020S, GA7021: From middle of December 2005 production
- GA9020: From serial No.6991Y (December 2005)
- GA9020S: From serial No.151Y (February 2006)
- MT900: From serial No.4121Y (December 2005)
- MT901: From serial No.3763Y (January 2006)
- M907: From serial No.221Y (January 2006)
- M908: From serial No.221Y (January 2006)