

Subject ▶ Change on compression spring 46, gear housing cover, etc.

For Models ▶ HM1800

Description

1.Compression spring 46

*The compression spring 46 on the gear housing cover side will be replaced by a compression spring 12. See the figures below.

*The compression spring 46 on the rear case side will be discontinued.

2.Gear housing cover

The portion which accepts the compression spring will be changed in shape as shown in the figures below.


3.Handle base

*The handle bases will be changed in shape as shown in the figures below.


*Note: Not only the handle base on the gear housing cover side but also that on the rear case side will be changed.

4.The rubber sleeve 8 will be changed in shape as shown in the figures below.



► Current



Handle base seen
From side A



► New



Changed

Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
95	Compression spring 46 233051-0		1	No	Compression spring 12 233149-3		1	For gear housing cover side
95	Compression spring 46 233051-0		1					For rear case side
52	Gear housing cover 316311-6		1	No	Gear housing cover 316792-4		1	
42	Handle base 322481-1		2	<=	Handle base 322847-5		2	
40	Rubber sleeve 8 262526-2		1	No	Rubber sleeve 8 262538-5		1	

Note

- * <= mark indicates that the new type part can be substituted for the the current type part.
- * The current type parts and the new type parts are interchangeable as a set of all the above parts.

Implementation

From July, 1995 , From Serial Number 7671E