







- Subject** ▶ Change on impact bolt, cylinder liner complete, etc.
- For Models** ▶ HR3520B, HR3520, HR3521, HR3510, HR3511 and HR3501 (Rotary Hammer)
- Description** ▶ 1. For Model HR3520B only
The impact bolt will be changed as shown in the figures below.
The steel balls 7.9 will be discontinued.

▶ Current	▶ New
 <p>Steel ball 7.9</p> <p>Hole for steel ball</p>	 <p>Spline</p>

- 2. For Model HR3520B only
The cylinder liner complete will be changed as shown in the figures below.

▶ Current	▶ New
 <p>Groove</p>	

- 3. For all the above models
The striker will be changed as shown in the figures below.
To differentiate the new type from the current type, a line will be added to the new type striker.

▶ Current	▶ New
 <p>ø18.2mm (23/32")</p>	 <p>ø17.4mm (11/16")</p> <p>A line will be added.</p>

Interchangeability(I/C)

Item No.	Curret part	Q'ty	I/C	New part	Q'ty	Note
038	Impact bolt 322217-8	1	No	Impact bolt 322805-1	1	For HR3520B
037	Cylinder liner complete 152337-2	1	No	Cylinder liner complete 152493-8	1	For HR3520B
007	Striker 322197-8	1	<=	Striker 322806-9	1	For all the above models
008	Steel ball 7.9 216004-4	3				For HR3520B

Note

1. For Model HR3520B only
The current type parts and the new type parts are interchangeable as a set of all the above parts.
2. Interchangeability mark:
<= mark indicates that the new type part can be substituted for the current type part.

Implementation

HR3520B: From serial No. 17899E

HR3520 : From serial No. 91210E

HR35221, HR3510, HR3511 and HR3501: Discontinued