



Subject ▶ Change on Impact Bolt, Tool Holder and addition of Cap

For Models ▶ HR3850B,HR3850,HR3851(Rotary Hammer Drills)


Note ▶ This information applies to
 HR3850B ----- All countries
 HR3850,HR3851----- U.S.A. only

Description ▶ As illustrated below, Impact Bolt and Tool Holder have been changed for improvement in endurance. Cap has been added as dust cover.


► Current



Tool Holder



Impact Bolt



Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
51	Impact Part 322218-6		1	No	Impact Bolt 323718-9		1	Interchangeable as a set
58	Tool Holder 322221-7		1	No	Tool Holder 323717-1		1	
117					Cap 421596-2		1	

Implementation

HR3850B : From serial No. 38496E (Mar.1997)
 HR3851 : From serial No. 30478E (Mar. 1997)
 HR3850 : Discontinued for U.S.A.