



SERVICE BULLETIN

MODEL

RB397

BULLETIN NO.


RB397-MK2

DATE of Change

April 1, 2012

When clean up at the cutter area is required, service person should unscrew the chrome color bolts only and should not unscrew the black bolts on the Arm Cover. In order to secure this, 2 pcs of Black Hex bolt M3x5 (BB40711) were changed Torx bolt M3x5(BB86701).

Old Hex bolt BB40711 was discontinued.



Changed to Torx Type

OLD				NEW		
Part No.	Part Code	Description	Qty	Part Code	Description	Qty
2	BB40711	BOLT 3X5 Hex type bolt	2	BB86701	TORX BOLT 3X5 Torque type bolt	2