MAX EUROPE BV

SERVICE BULLETIN

MODEL	
RB398/518/218	**Aug 2016** **Serial: 166********

SUBJECT: Parts Change (Shaft for Cutter Lever)

Below parts has been modified. Performance & durability of tools are same as previous version.
Modified parts are installed to the production from Jun/2016.

↓ ( )RB518

Diagram No	11(79)	Part Code	RB11846
Part Name	SHAFT		

OLD



1. No bump, smooth surface
2. PIN 1686 goes here

Diagram No	10(25)	Part Code	FF51686
Part Name	PIN 1686		

OLD



Diagram No	11(79)	Part Code	RB12710
Part Name	SHAFT		

NEW



1. Bump exists.
2. No need for PIN 1686

Diagram No		Part Code	
Part Name			

NEW

This part has been terminated

OLD Version				NEW Version		
ITEM#	PART#	DESCRIPTION	PARTS SUPPLY	ITEM#	PART#	DESCRIPTION
11(79)	RB11846	SHAFT	Yes	11(79)	RB12710	SHAFT
10(25)	FF51686	PIN 1686		10(25)		

Interchangeability; YES