TECHNICAL INFORMATION

72334

Subject ► Change of Base Complete and Rubber Sleeve 48

For Models ► BO4550, BO4553

Country ► All countries

Description ► Base complete and Rubber sleeve 48 have been changed as illustrated below.

► Current	► New
	 Base complete (154657-0) includes Rubber sleeve 48.

Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
022	Base Complete 151236-5		1	No	Base Complete 154657-0		1	
018	Rubber Sleeve 48 262512-3		1					

Implementation

BO4553: From December, 2004 production
BO4550: Discontinued since October, 1994
The change of the part for repair has been implemented around December, 2004 production.