


# T ECHNICAL INFORMATION

- Subject** ▶ Change of Motor Housing
- For Models** ▶ 9563, 9563C, 9563CV, 9564, 9564C, 9564CV, 9564CVL, 9565, 9565C, 9565CV, 9565CVL, 9566C, 9566CV
- Country** ▶ All countries
- Description** ▶ Motor housing has been modified as illustrated below.



## Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
033	Motor Housing 183407-6		1	Yes	Motor Housing 183740-6		1	
033	Motor Housing Complete 153294-7		1	Yes	Motor Housing Complete 153771-9		1	
033	Motor Housing Complete 153295-5		1	Yes	Motor Housing Complete 153772-7		1	
033	Motor Housing Complete 153557-1		1	Yes	Motor Housing Complete 153773-5		1	
033	Motor Housing Complete 153558-9		1	Yes	Motor Housing Complete 153774-3		1	
033	Motor Housing 183573-9		1	Yes	Motor Housing 183741-4		1	

## Implementation

- 9564: From serial No. 21735E (Aug., 2003)
- 9565: From serial No. 72918E (Aug., 2003)
- 9565C: From serial No. 21214E (Aug., 2003)
- 9565CV: From serial No. 55012E (Aug., 2003)
- 9565CVL: From serial No. 7855E (Aug., 2003)
- 9566C: From serial No. 2463E (Aug., 2003)

To be implemented around Sep., 2003:  
9563, 9563C, 9564C, 9564CV, 9564CVL, 9566CV

9563CV: Discontinued since Jan., 2003