


TECHNICAL INFORMATION



68904

- Subject** ▶ Change of Chip Cover
- For Models** ▶ 2012NB
- Country** ▶ All countries
- Description** ▶ A $\phi 10$ mm(3/8") hole has been punched on Chip cover.
The part No. of the Chip cover has been changed for distinction.



Chip Cover
(165379-7)

Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
134	Chip Cover 165272-5		1	Yes	Chip Cover 165379-7		1	

Implementation

From serial No. 22216K (Sep., 2003)