



- Subject** ▶ Change on Motor Bracket Complete and Bearing Retainer
- For Models** ▶ 3600H, 3600HA, 3612BR, 3600NB, 3600NBR, 3612BRA, 3612B(Router)
- Description** ▶ Screws for fixing Bearing Retainer 50 have been reduced from four to two.  
Accordingly Bearing Retainer 50 and Motor Bracket Cpmplete have been changed.  
All parts Numbers remains the same.

## 1. For Model:3600H, 3600HA



## 2. For Model:3612BR, 3600NB, 3600NBR, 3612BRA, 3612B



## Implementation

- 3600H : From serial No.55537E(Feb.1997)
- 3600HA : Discontinued
- 3612BR : From serial No.268215E(Feb.1997)
- 3600NB : Discontinued
- 3600NBR : Discontinued
- 3612BRA : Discontinued
- 3612B : Discontinued