

- Subject** ▶ Change of Switch, Power Supply Cord, etc.
- For Models** ▶ M101, M362, M511, M515, M516, M992, SR1600, SR1800, 1125, 1901, 3608B, 3620, 3621, 4100R, 4103KB, 4101RH, 4105KB, 4200N, 5000SB, 5000SBR, 5011NB, 5012B, 5600BR, 5801B
- Country** ▶ See page 2.
- Description** ▶ The followings have been implemented to comply with UL or CSA Standards.
- 1) Change of Switch (For all models above)  
The new Switches don't come with four M3.5 Pan Head Screws.
  - 2) Addition of Terminal Block (For M362, 3620, 3621 only)
  - 3) Change of Power Supply Cord, addition of Cord Guard, Strain Relief and Pan Head Screw  
(For 3621 only) < molded cord guard → unmolded one >,  
Consequently, wirings have been changed.

## For Model 3620, 3621, M362

### ● Change of Switch

	▶ Current	▶ New
Manufacturer	OMRON	FUJISOKU
Cat. No.	C2M-M1T	SGE115CDY-5
Terminal Screws	(These come with Switch)	Pan Head Screws M3.5 x 7
Part No.	651236-0	651280-7

### ● Change of Wiring

	▶ Current	▶ New
Wiring		

- Noise Suppressor is not used in some countries and areas.

## For all Models except 3620, 3621, M362

### ● Change of Switch

	▶ Current	▶ New
Manufacturer	OMRON	FUJISOKU
Cat. No.	C2M-M1T	SGE215C
Terminal Screws	(These come with Switch)	Pan Head Screws M3.5 x 7
Part No.	651236-0	650210-5

### ● Change of Wiring

	▶ Current	▶ New
Wiring		

- Noise Suppressor is not used in some countries and areas.

## Interchangeability(I/C)

## For 3620, 3621, M362

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
012	Switch C2M-M1T 651236-0		1	No	Switch SGE115CDY-5 651280-7		1	Interchangeable as a set
3620: 705 3621: D02 M362: 703					Pan Head Screw M3.5x7 652008-6		2	
3620: 707 3621: D03 M362: 704					Terminal Block 1P 654532-5		1	

## For 3621 only

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
008	Power Supply Cord AWG#18-2-2.0 664424-0		1	No	Power Supply Cord AWG#18-2-2.5 664013-1		1	Interchangeable as a set with Power Supply Cord
009					Cord Guard 8-85 682502-4		1	
010					Strain Relief 687001-1		1	
011					Pan Head Screw M4x18 911133-5		2	

## For all Models except 3620, 3621, M362

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
See below	Switch C2M-M1T 651236-0		1	→	Switch SGE215C 650210-5		1	Interchangeable as a set
See below					Pan Head Screw M3.5x7 652008-6		4	

## Interchangeability mark ;

The arrow → means that the current part is substituted for the new.

## Item No. of Switch

Model	M101	M511	M515	M516	M992	SR1600	SR1800	1125	1901	3608B	4100R	4101RH
Item No.	014	007	040	041	006	040	041	011	014	028	054	054

Model	4103KB	4105KB	4200N	5000SB	5000SBR	5011NB	5012B	5600BR	5801B
Item No.	004	046	002	009	005	057	034	011	016

## Item No. of Pan Head Screw M3.5 x 7

Model	M101	M511	M515	M516	M992	SR1600	SR1800	1125	1901	3608B	4100R	4101RH
Item No.	700	700	700	700	700	700	700	706	700	700	700	D01

Model	4103KB	4105KB	4200N	5000SB	5000SBR	5011NB	5012B	5600BR	5801B
Item No.	700	704	705	700	700	700	700	700	700

## Note

## Applicable countries

	Model	Countries
Continued Models	3620	All countries
	3621	U.S.A., Mexico, Panama, Guam
	4101RH	Australia, New Zealand
	4105KB	Austria, France, Germany, Italy, Netherlands, Russia, Spain, Sweden, U.K., Algeria, Reunion, Turkey, Australia, New Zealand
	4200N	New Zealand
	5012B	Tahiti
Discontinued Models	M101, M362, M511, M515, M516, M992, SR1600, SR1800, 1125, 1901, 3608B, 4100R, 4103KB, 5000SB, 5000SBR, 5011NB, 5600BR, 5801B	Countries where Switch (651236-0) has been used as replacement part.

## Implementation

M101: Discontinued since April, 1992  
M362: Discontinued since April, 1993  
M511: Discontinued since July, 1992  
M515: Discontinued since August, 1991  
M516: Discontinued since August, 1991  
M992: Discontinued since April, 1993  
SR1600: Discontinued since April, 1995  
SR1800: Discontinued since April, 1995  
1125: Discontinued since April, 1994  
1901: Discontinued since May, 1999  
3608B: Discontinued since April, 1993  
3620: From December, 2002 production  
3621: From December, 2002 production  
4100R: Discontinued since April, 1993  
4103KB: Discontinued since October, 1992  
4101RH: From December, 2002 production  
4105KB: From December, 2002 production  
4200N: From December, 2002 production  
5000SB: Discontinued since April, 1989  
5000SBR: Discontinued since June, 1991  
5011NB: Discontinued since April, 1989  
5012B: From December, 2002 production  
5600BR: Discontinued since April, 1995  
5801B: Discontinued since May, 1995