


T ECHNICAL INFORMATION



73755
August, 2005

- Subject** ▶ Modification of Armature Ass'y
- For Models** ▶ 3707FC, 3708FC
- Country** ▶ All countries
- Description** ▶ A groove has been added into Armature shaft.
Consequently, Part number of Armature ass'y has been changed.
See illustration below.



Interchangeability(I/C)

| Item No. | Current part | | Q'ty | I/C | New part | | Q'ty | Note |
|----------|---------------------------------|--|------|-----|---------------------------------|--|------|------|
| 020 | Armature Ass'y 115V 517566-8 | | 1 | ← | Armature Ass'y 115V 517616-9 | | 1 | |
| 020 | Armature Ass'y 240V 517569-2 | | 1 | ← | Armature Ass'y 240V 517619-3 | | 1 | |
| 020 | Armature Ass'y 115V 518551-4 | | 1 | ← | Armature Ass'y 115V 518554-8 | | 1 | |

Interchangeability mark ;

The arrow ← means that the new part can be substituted for the current.

Implementation

From August, 2005 production.