


- Subject** ▶ Modification of DC motor
- For Models** ▶ 4070D, 4071D, 6016D, 6017D, 6018D, 6019D, 6096D, 6223D, 6226D, 6227D, 6327D, 6228D, 6328D, M010, MEU003
- Country** ▶ All countries
- Description** ▶ DC motor have been modified for further increase of durability on its brush arm as illustrated below.



Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
005	DC motor 629691-4		1	←	DC motor 629776-6		1	4070D, 4071D, M010
004	DC motor 629726-1		1	←	DC motor 629778-2		1	6096D
6016D, 6017D, 6018D: 010 6019D: 011	DC motor 629708-3		1	←	DC motor 629779-0		1	6016D, 6017D, 6018D, 6019D
036	DC motor 629720-3		1	←	DC motor 629781-3		1	6223D
016	DC motor 629748-1		1	←	DC motor 629785-5		1	6226D
016	DC motor 629750-4		1	←	DC motor 629787-1		1	6227D, 6327D
016	DC motor 629752-0		1	←	DC motor 629789-7		1	6228D, 6328D

Interchangeability mark ;

The arrow ← means that the new part can be substituted for the current.

Implementation

4070D: From serial No.58438E (The implementation date will be informed later.)

M010: Discontinued since Aug.,1992

The remaining models: To be informed later