


Subject ▶ Change of Screw for Adjusting on Vertical Cut

For Models ▶ 4157KB, 5007F, 5007FA, 5007NB, 5007NBA, 5007NH, 5007NL, 5008NB, 5008NBA, 5037NB, 5037NBA, 5057KB, 5077B, 5177B, 5277B, 5277NB, 5620D, 5621D, 5630D

Country ▶ All countries

Description ▶ Screw has been changed as illustrated below.



Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
See below	+Screw M5x12 ----- 266180-4		*	Yes	Hex. Socket Head Screw M5x12 ----- 266213-5		*	* Quantity depends on the Model Number.

Model	4157KB	5007F	5007FA	5007NB	5007NBA	5007NH	5007NL	5008NB	5008NBA
Item No.	073, 075	062	062	062	062	056, 064, 065	056, 064, 065	066	066
Model	5037NB	5037NBA	5057KB	5077B	5177B	5277B	5277NB	5620D	5621D
Item No.	068	068	073, 075	065	064	064	064	054	059
Model	5630D								
Item No.	059								

Implementation

5277NB: From initial production

The remaining models: To be informed later