

T ECHNICAL INFORMATION



63024

- Subject** ▶ Change of Ball Bearing 6002DDW
- For Models** ▶ BO3700, BO5000, BO5001, BO6030, 3606, 3700, 3700B, 3701, 3702, 3702B, 3706, 4401, 5017RKB, 5103R, 5143R, 5603R, 5703R, 5705R, 5901B, 5902B, 5903, 5903R, 8406C, 9015A, 9046, 9741
- Country** ▶ All countries
- Description** ▶ For standardization, Part No. of Ball Bearing 6002DDW has been changed from 211227-9 to 211236-8. However, Ball Bearing 6002DDW itself remains unchanged.

Interchangeability(I/C)

| Item No. | Current part | | Q'ty | I/C | New part | | Q'ty | Note |
|-----------------|----------------------------------|--|------|-----|----------------------------------|--|------|---|
| See note below. | Ball Bearing 6002DDW 211227-9 | | 1 | Yes | Ball Bearing 6002DDW 211236-8 | | 1 | For all Models on the subject except 9046 |
| | Ball Bearing 6002DDW 211227-9 | | 2 | Yes | Ball Bearing 6002DDW 211236-8 | | 2 | For 9046 |

Note

| Model | BO3700 | BO5000 | BO5001 | BO6030 | 3606 | 3700 | 3700B | 3701 | 3702 | 3702B | 3706 | 4401 | 5017RKB |
|----------|--------|--------|--------|--------|------|------|-------|------|------|-------|------|------|---------|
| Item No. | 018 | 015 | 015 | 032 | 014 | 015 | 020 | 015 | 016 | 015 | 014 | 021 | 010 |

| Model | 5103R | 5143R | 5603R | 5703R | 5705R | 5901B | 5902B | 5903 | 5903R | 8406C | 9015A | 9046 | 9741 |
|----------|-------|-------|-------|-------|-------|-------|-------|------|-------|-------|-------|-----------|------|
| Item No. | 060 | 070 | 007 | 010 | 010 | 006 | 006 | 042 | 047 | 006 | 040 | 066 & 069 | 008 |

Implementation

Machines manufactured in MJ (Makita Japan)

BO5000: Discontinued since Apr.,1998
 BO5001: From serial No.17533E (Jan., 2001)
 BO6030: From serial No.2812E (Jan., 2001)
 3606 : From serial No.64885E (Jan., 2001)
 3700 : Discontinued since Oct., 1991
 3700B : From serial No.402883E (Jan., 2001)
 3701 : From serial No.424107E (Feb., 2001)
 3702 : From serial No.11817E (Feb., 2001)
 3702B : From serial No.15232E (Jan., 2001)
 4401 : Discontinued since Oct., 1994
 5103R : From serial No.21330E (Jan., 2001)
 5143R : From serial No.19875E (Jan., 2001)
 5901B : From serial No.7156E (Feb., 2001)
 5902B : From your order received by us in/after Apr., 2001
 8406C : From serial No.11242E (Jan., 2001)
 9015A : From your order received by us in/after Apr., 2001
 9046 : From serial No.66642E (Jan., 2001)
 9741 : From serial No.36032E (Jan., 2001)

Machines manufactured in MCA (Makita Corporation of America)

BO5000 : Discontinued since Apr.,1998
 BO5001 : From serial No.209137A (Dec., 2000)
 3606 : To be informed later
 3706 : From initial production

Machines manufactured in MCC (Makita (China) Co., Ltd)

BO3700 : From serial No.69308K (May, 2001)
 5903R : From initial production

Machines manufactured in MME (Makita Manufacturing Europe Ltd.)

5017RKB : From serial No.1341G (Apr., 2001)
 5603R : From serial No.68931G (Apr., 2001)
 5703R : From serial No.192939G (Apr., 2001)
 5705R : From serial No.8715G (Apr., 2001)
 5903R : From serial No.152121G (Apr., 2001)

Machines manufactured in MBR (Makita do Brasil)

3702B : To be informed later