




T ECHNICAL INFORMATION



62358

- Subject** ▶ Change of Hook
- For Models** ▶ 6823, 6823TP, 6824, 6824TP, 6825, 6825TP, DP3002, DP3003, DP4000, DP4001, DP4002, DP4003, JS1300
- Country** ▶ All countries
- Description** ▶ For better operation, Hook has been changed as illustrated below.



▶ Current	▶ New
 Hook 416996-9	 Hook 417625-7

Interchangeability(I/C)

Item No.	Current part	Q'ty	I/C	New part	Q'ty	Note
6823, 6823TP, DP3002, DP3003, JS1300 : 031	Hook ----- 416996-9	1	←	Hook ----- 417625-7	1	
6824, 6824TP, 6825, 6825TP : 028						
DP4000, DP4001, DP4002, DP4003 : 032						

Note

Interchangeability mark ; ← means that the new part is substituted for the current.

Implementation

- 6823 : From serial No.15843E (Oct., 2000)
- 6824 : From serial No.44089E (Oct., 2000)
- 6825 : From serial No.118883E (Oct., 2000)
- DP3002 : From serial No.1048E (Oct., 2000)
- DP3003 : From serial No.1124E (Oct., 2000)
- DP4000 : From serial No.3538E (Nov., 2000)
- DP4001 : From serial No.1804E (Nov., 2000)
- DP4002 : From serial No.3541E (Nov., 2000)
- DP4003 : From serial No.1905E (Nov., 2000)
- JS1300 : From serial No.1085E (Oct., 2000)
- 6823TP 6824TP, 6825TP : From your order received by us in/after Feb., 2001