


# TECHNICAL INFORMATION

- Subject** ▶ Change of Pan Head Screws
- For Models** ▶ 6904H, 6904V, 6904VH, 6905H
- Country** ▶ All countries
- Description** ▶ Pan head screws have been replaced by the ones with adhesive to join the left-half and the right-half of housing set together as illustrated below.



## Interchangeability(I/C)

Item No.	Current part	Q'ty	I/C	New part	Q'ty	Note
6904H, 6904VH: 040 6904V: 046	Pan Head Screw M4x20 911138-5	7	←	Pan Head Screw M4x20 911536-3	7	6904H, 6904V, 6904VH
035	Pan Head Screw M4x25 911148-2	8	←	Pan Head Screw M4x25 911546-0	8	6905H

### Interchangeability mark ;

The arrow ← means that the new part can be substituted for the current.

## Implementation

- 6904H: Discontinued since April 1996
- 6904V: From serial No. 2643E (June 1997)
- 6904VH: From serial No. 34741E (June 1997)
- 6905H: From serial No. 47987E (June 1997)