





Subject ▶ Change on field

For Models ▶ 6905H (Impact Wrench)

Description ▶ The method of connecting the field coil to the terminals will be changed as follows.

▶ Current	▶ New
<p>Ends of field coil are connected to each nearest terminals.</p> 	<p>Ends of field coil will be connected to their opposite terminals.</p> 

As a result, the method of connecting the lead wires to field will be changed as follows. (Note: The method of connecting the field to the switch will remain unchanged.)

▶ Current	▶ New
	

Interchangeability(I/C)

Item No.	Current part		Q'ty	New part		Q'ty	I/C	Note
28	Field 634105-0		1	Field 634175-9		1	<=	100V
28	Field 634106-8		1	Field 634176-7		1	<=	115V
28	Field 634107-6		1	Field 634177-5		1	<=	200V
28	Field 634108-4		1	Field 634178-3		1	<=	220V
28	Field 634109-2		1	Field 634179-1		1	<=	240V

Note

Interchangeability mark : <= mark indicates that the new type part can be substituted for the current type part.

Implementation schedule

From serial No.5880E