

# T ECHNICAL INFORMATION

- Subject** ▶ Changes of Spindle and Ring Spring 9
- For Models** ▶ 6940D
- Country** ▶ All countries
- Description** ▶ Spindle and Ring Spring 9 have been changed as illustrated below.

	▶ Current	▶ New
Spindle		
Ring Spring 9		

## Interchangeability(I/C)

Item No.	Current part	Q'ty	I/C	New part	Q'ty	Note
043	Ring Spring 9 231961-5	1	←	Ring Spring 9 231990-8	1	All countries
046	Spindle 322714-4	1	No	Spindle 323922-0	1	U.S.A., Canada, Southeast Asia
046	Spindle 322760-7	1	No	Spindle 323921-2	1	European countries

## Note

- 1) Interchangeability mark ; ← means that the new part is substituted for the current.
- 2) Ring Spring 9 will be deformed when removed from Spindle.  
So, it is not recommendable to use the same Ring Spring again for repairing.

## Implementation

U.S.A., Canada, Southeast Asia : From serial No.502821E (Mar.,1999)  
European countries : From serial No.503523E (Mar.,1999)