





Subject ▶ Addition of sponge sheet to handle

For Models ▶ 9005B, 9006B, 9005BS (Disc Grinders)

Description ▶ As illustrated below, sponge sheet has been added against damage to power supply cord.

	▶ Current	▶ New
U.S.A., Guam, Canada, Australia, Netherlands, United Kingdom, Italy, Greece, Austria, Finland, France, New Zealand, Reunion, Algeria		
Other countries		

Interchangeability(I/C)

Item No.	Current part		Q'ty	New part		Q'ty	I/C	Note
44	Hadle set 182418-8		1	Hadle set 182853-0		1	<=	U.S.A., Guam, Canada, Australia, Netherlands, United Kingdom, Italy, Greece, Austria, Finland, France, New Zealand, Reunion, Algeria
44	Hadle set 181346-4		1	Hadle set 182854-8		1	<=	Other countris
44				Sponge sheet 421565-3		1		

Note

Interchangeability mark : <= means that the new part can be substituted for the current. The current handle set can be used for replacement when you paste the sponge sheet to it. The new handle set is supplied to you with the sponge sheet pasted.

Implementation

9005B : From serial No.1179869E

9006B : From serial No.90021E

9005BS : From your next order