


Subject ▶ Changes on screws fixing bearing box

For Models ▶ 9005B,9006B,9005BS and PC1100 (Disc grinders and Concrete planer)

Description ▶ As described below, screws have been changed for fixing more securely.

	Current	New
9005B,9006B 9005BS	Tapping screw	Hex.socket head bolt(with bond)
PC1100		Pan head screw



Interchangeability(I/C)

Item No.	Current part	Q'ty	I/C	New part	Q'ty	Note
31	Tapping Screw CT 4X16 ----- 266034-5	4	<=	Hex.Socket Head Bolt M4X14 ----- 266148-0	4	9005B,9006B,9005BS
29	Tapping Screw CT 4X25 ----- 266040-0	4	<=	Pan Head Screw M4X22 ----- 911141-6	4	PC1100

Note

Interchangeability mark:<= means that the new part can be substituted for the current.

Implementation

9005B : From serial No. 1226329E
 9005BS : From your next order
 9006B : From serial No. 100474E
 PC1100 : From serial No. 26790E