


**Subject** ▶ Change on Armature

**For Models** ▶ 9020L, 9027, 9027L, 9027S, 9029, 9029S, 9037, 9037S, 9039, 9039S (Disc grinders)

**Description** ▶ As in the following figures



## Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
5	Armature ass'y 518486-9		1	<=	Armature ass'y 516656-4		1	9020L and 9027 for U.S.A. and Canada only
5	Armature ass'y 514971-0		1	<=	Armature ass'y 516656-4		1	115V $\uparrow$ 9027
5	Armature ass'y 514973-6		1	<=	Armature ass'y 516658-0		1	220V $\uparrow$ 9027S
5	Armature ass'y 514974-4		1	<=	Armature ass'y 516659-8		1	240V $\uparrow$ 9029
5	Armature ass'y 516501-3		1	<=	Armature ass'y 516661-1		1	115V $\uparrow$ 9029S
5	Armature ass'y 516503-9		1	<=	Armature ass'y 516663-7		1	220V $\uparrow$ 9037
5	Armature ass'y 516503-9		1	<=	Armature ass'y 516664-5		1	240V $\uparrow$ 9037S 9039 9039S

## Note

- (1) Interchangeability mark: <= means that the new part can be substituted for the current.
- (2) Each current armature ass'y has been discontinued, and its stock should be abandoned.
- (3) The following armature assemblies in your stock can be used for replacement, although they have been discontinued.  
B33702, B33704, B33705, B33706, B33707  
(Refer to TEC-8/95 dated Feb. 6, 1995 as to the details of these parts.)

## Implementation

9027: From serial No. 30572E  
 9027S: From serial No. 13553E  
 9029: From serial No. 80676E  
 9029S: From serial No. 65301E  
 9037: From serial No. 6118E  
 9037S: From serial No. 3235E  
 9039: From serial No. 14387E  
 9039S: From serial No. 8685E

## Note

As to the products of Makita Manufacturing Europe Ltd., this modification will be implemented around September, 1995.