


T ECHNICAL INFORMATION



64114

- Subject** ▶ Change of Pan Head Screw M5x18
- For Models** ▶ 9040L, 9047, 9047L, 9047S, 9049, 9049S, 9057, 9057S, 9059, 9059S
- Country** ▶ All countries
- Description** ▶ 4 pcs. of Pan Head Screw M5x18 without adhesive have been replaced by ones with adhesive.



Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
See note below.	Pan Head Screw M5x18 911226-8		4	←	Pan Head Screw M5x18 911230-7		4	

Interchangeability mark ;

The arrow ← means that the new part can be substituted for the current.

Note

Item No. for Pan Head Screw M5 x18

No.031: 9040L

No.033: 9047, 9047L, 9047S, 9049, 9049S, 9057, 9057S, 9059, 9059S

Implementation

Machines manufactured in MJ (Makita Japan)

9047: From serial No.55091E (July, 2001)

9047S: From serial No.4622E (July, 2001)

9049: From serial No.70655E (July, 2001)

9057: From serial No.11577E (July, 2001)

9059: From serial No.44256E (July, 2001)

9040L, 9047L, 9049S, 9057S, 9059S: To be informed later

Machines manufactured in MME (Makita Manufacturing Europe Ltd.)

To be informed later