


**Subject** ▶ Change on bearing box

**For Models** ▶ 9047,9047S,9057,9057S,9047L (Disc Grinders)

**Description** ▶ As illustrated below, bearing box has been changed for standardization.



### Interchangeability(I/C)

Item No.	Current part	Q'ty	I/C	New part	Q'ty	Note
27	Bearing Box 316854-8	1	Yes	Bearing Box 316855-6	1	

### Implementation

- 9047 ----- From serial No. 4895G (Manufactured in U.K.)  
From serial No. 28210E (Manufactured in Japan)
- 9047S ----- From serial No. 3795G (Manufactured in U.K.)  
From serial No. 3853E (Manufactured in Japan)
- 9057 ----- From serial No. 1289G (Manufactured in U.K.)  
From serial No. 4854E (Manufactured in Japan)
- 9057S----- From serial No. 1425G (Manufactured in U.K.)
- 9047L ----- From serial No. 1001G (Manufactured in U.K.)