





# TECHNICAL INFORMATION




57608

- Subject** ▶ Change in Switch and Noise suppressor
- For Models** ▶ 9047S, 9049S, 9057S, 9059S, 9027S, 9029S, 9037S, 9039S
- Country** ▶ See "Note" of "Interchangeability (I/C)".
- Description** ▶ The current switches cannot be supplied by our supplier ( production discontinued).

	▶ Current	▶ New
Switch	 <p>Change in delay mechanism</p> <p>Change in Noise Suppressor receiving part</p>	
Noise Suppressor (Changed to smaller one to suit to the modified Noise suppressor receiving part of Switch)		

## Notes in Repairing

The combination of New switch and Current noise suppressor might result in the interference of a rib inside Handle.  
So, remove the Rib before installation.



## Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
9027S/9029S/9037S/ 9039S : 044 9047S/9049S/9057S/ 9059S : 045B	Switch 651147-9		1	Yes	Switch 651147-9		1	Austria, France, Germany, Italy, Netherlands, Spain, U.K., Finland, Norway, Switzerland, Sweden, Kuwait, Saudi Arabia, Turkey, Algeria, South Africa, Reunion Brazil, Bhutan (Only machines manufactured in U.K.)
9027S/9029S/9037S/ 9039S : 044A 9047S/9049S/9057S/ 9059S : 045D	Switch 651150-0		1	Yes	Switch 651150-0		1	
9027S/9029S/9037S/ 9039S : 044B 9047S/9049S : 045C	Switch 651151-8		1	Yes	Switch 651151-8		1	
9027S/9029S/9037S/ 9039S : 046A 9047S/9049S/9057S/ 9059S : 049A	Noise Suppressor 645216-6		1	Yes	Noise Suppressor 645216-6		1	

## Enforcement schedule

Switch (Part No.651147-9)

9047S : From serial No.8911G

9049S : From serial No.56624G

9057S : From your next order in/after Mar.,1999

9059S : From serial No.8903G

Switch (Part No.651150-0)

9047S : From serial No.9101G

9049S : From serial No.60536G

9059S : From serial No.9287G

Switch (Part No.651151-8)

Around Sep.,1999