

# TECHNICAL INFORMATION



Y04375

- Subject** ▶ Introduction of Gear Housing Assembly
- For Models** ▶ 9040L, 9047, 9047L, 9047S, 9049, 9049S, 9057, 9057S, 9059, 9059S
- Country** ▶ All countries
- Description** ▶ Gear housing assembly (Part No. 125201-0) has become available for easier replacement.  
It consists of the following parts.
- Gear housing complete (151859-9)
  - Compression spring 12 (233031-6)
  - Pin 6 (256445-2)
  - Pin cap (416132-7)

## Interchangeability(I/C)

| Item No. | Current part |  | Q'ty | I/C | New part                          |  | Q'ty | Note |
|----------|--------------|--|------|-----|-----------------------------------|--|------|------|
| 016      |              |  |      |     | Gear Housing Assembly<br>125201-0 |  | 1    |      |

## Implementation

Available since Nov., 2003.