


# T ECHNICAL INFORMATION



68182A

- Subject** ▶ Modification of Switch Lever
- For Models** ▶ 5007F, 5007FA, 900, 910, 9514B, 9514BH, M954, N9514B
- Country** ▶ All countries
- Description** ▶ Switch lever has been modified as illustrated below.  
Consequently Switch has also been changed.



## Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
See below.	Switch SLE 6A 651514-8		1	←	Switch SLE 6A 651514-8		1	

### Interchangeability mark ;

The arrow ← means that the new part can be substituted for the current.

Item No. of Switch

Model	5007F	5007FA	900	910	9514B	9514BH	M954
Item No.	068		024		013		

## Note

The wiring, assembling and Part No. remain the same.

## Implementation

### MKC plant

5007F: From serial No. 43401Y (Around June, 2003)

5007FA: From serial No. 4321Y (Around July, 2003)

### MCA plant

N9514B: Since around July 2003 production

### MJ plant

9514B, 9514BH: Since around July 2003 production

900, 910: Discontinued since May 1999

M954: Discontinued since April 1993