






# TECHNICAL INFORMATION



62568

- Subject** ▶ Change of Spiral Bevel Gears
- For Models** ▶ 9523NB, 9523NBH, 9524NB  
This modification applies only to the machines manufactured in MCC (Makita (China) Co., Ltd.).
- Country** ▶ All countries
- Description** ▶ The Spiral Bevel Gears in subject have been changed. There is a difference to distinguish the new Spiral Bevel Gears from the current ones. See the illustration below for the difference.



	▶ Current	▶ New
Spiral Bevel Gear 11	 No Grooves	 Grooves
Part No.	226733-1	226799-1
Spiral Bevel Gear 36	 Stamp of Z	 No stamp
Part No.	226728-4	226798-3

## Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
006	Spiral Bevel Gear 11 226733-1		1	No	Spiral Bevel Gear 11 226799-1		1	Interchangeable as a set
041	Spiral Bevel Gear 36 226728-4		1	No	Spiral Bevel Gear 36 226798-3		1	

## Implementation

To be informed later