



# TECHNICAL INFORMATION

- Subject** ▶ Change of Switch Lever and Compression Spring 4
- For Models** ▶ 9523NB, 9523NBH, 9524NB, 9525NB, 9526NB, 9526NBH, 9527NB, 9528NB
- Country** ▶ All countries
- Description** ▶ Switch Lever and Compression Spring 4 have been changed for quick repairing as shown below.

▶ Current	▶ New
 <p style="text-align: center;">Switch Lever (415953-4)      Compression Spring 4 (233153-2)</p>	<p style="text-align: left; margin-left: 20px;">The Shape changed here.</p>  <p style="text-align: right; margin-right: 20px;">The new spring is shorter by 3 mm than the current one.</p> <p style="text-align: center;">Switch Lever (417352-6)      Compression Spring 4 (233285-5)</p>

## Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
019	Switch Lever 415953-4		1	No	Switch Lever 417352-6		1	Interchangeable as a set
022	Compression Spring 4 233153-2		1	No	Compression Spring 4 233285-5		1	

## Implementation

### Machines manufactured in MCC (Makita (China) Co., Ltd.)

9523NB, 9523NBH, 9524NB, 9525NB, 9526NB, 9526NBH, 9527NB, 9528NB: To be informed later.

### Machines manufactured in MME (Makita Manufacturing Europe Ltd.)

9526NB, 9527NB, 9528NB: To be informed later.