

# T ECHNICAL INFORMATION



72864

**Subject** ▶ Change of Part Number and Description

**For Models** ▶ MT190, MT370, MT952, MT953, MT955, MT957, MT958, M193, M372, M905, M906, 9553NB, 9554NB, 9555NB, 9556NB, 9557NB, 9558NB, 9556PB, 9557PB, 9558PB

**Country** ▶ All countries

**Description** ▶ Part number and Description of current Resin washer have been changed as shown below.  
The goods themselves remain the same.

## Interchangeability(I/C)

| Item No.   | Current part             |  | Q'ty | I/C | New part                      |  | Q'ty | Note |
|------------|--------------------------|--|------|-----|-------------------------------|--|------|------|
| See below. | Resin Washer<br>681667-9 |  | 1    | Yes | Insulation Washer<br>681636-0 |  | 1    |      |

Item No. for Resin washer/ Insulation washer

| MT190 | MT370 | MT952 | MT953 | MT955 | MT957 | MT958 | M193 | M372 | M905 | M906 | 9553NB | 9554NB |
|-------|-------|-------|-------|-------|-------|-------|------|------|------|------|--------|--------|
| 020   |       | 005   |       | 006   |       |       | 020  |      | 006  |      | 005    |        |

| 9555NB | 9556NB | 9557NB | 9558NB | 9556PB | 9557PB | 9558PB |
|--------|--------|--------|--------|--------|--------|--------|
|        |        |        |        |        |        | 005    |

## Implementation

As soon as the current parts in stock run out.