



TECHNICAL INFORMATION



72590

- Subject** ▶ Elimination of Rubber Pin 4,
Change of Dust Collector Bracket
- For Models** ▶ 9900B, 9924DB
- Country** ▶ All countries
- Description** ▶ Rubber pin 4 has been eliminated from Dust collector bracket.

▶ Current	▶ New
<p>Dust collector bracket (152208-3) comes with rubber pin 4</p>  <p>Rubber pin 4 (263002-9)</p>	<p>Dust collector bracket (312810-6) has neither rubber pin 4 nor its installation hole.</p> 

Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
9900B: 015 9924DB: 034	Dust Collector Bracket 152208-3		1	Yes	Dust Collector Bracket 312810-6		1	
017	Rubber Pin 4 263002-9		1					

Implementation

9900B: Discontinued since May, 2001
9924DB: From serial No. 1108835E (January, 2005)