

# T ECHNICAL INFORMATION



90953


December 2010

**Subject** ▶ Change of brand logo position

**For Models** ▶ AT-3623, AT-3630, BBC231U, BBC300L

**Country** ▶ All countries

**Description** ▶ Brand logo position has been changed to Shaft pipe from Cushion as drawn below.



## Interchangeability(I/C)

| Item No. | Current part                    | Q'ty | I/C | New part                        | Q'ty | Note  |
|----------|---------------------------------|------|-----|---------------------------------|------|---|
| 050      | Cushion<br>424290-5             | 1    | No  | Cushion<br>424463-0             | 1    | BBC231U<br>Interchangeable as a set                                 |
| 031      |                                 |      |     | Makita logo label<br>819312-8   | 1    |   |
| 030      | Cushion<br>424291-3             | 1    | No  | Cushion<br>424463-0             | 1    | AT-3623<br>Interchangeable as a set                                 |
| 031      |                                 |      |     | Dolmar logo label<br>893388-3   | 1    |   |
| 031      | Shaft pipe complete<br>140284-9 | 1    | ←   | Shaft pipe complete<br>141097-1 | 1    | AT-3623, AT-3630  |
| 030      | Shaft pipe complete<br>140515-6 | 1    | ←   | Shaft pipe complete<br>141095-5 | 1    | BBC300L for Canada, USA   |
| 031      | Shaft pipe complete<br>140516-4 | 1    | ←   | Shaft pipe complete<br>141092-1 | 1    | BBC231U for Mexico  |
| 031      | Shaft pipe complete<br>140284-9 | 1    | ←   | Shaft pipe complete<br>141091-3 | 1    | BBC231U and BBC300L for all countries except Canada, Mexico and USA |

### Interchangeability mark:

The arrow ← means that the new part can be substituted for the current.

## Implementation

To be implemented from January 2011 MKC production