

TECHNICAL INFORMATION



93794
March 2012

Subject ▶ Change of Gear case assembly

For Models ▶ BBC231U, BBC300L, BC231UD, BC300LD, AT3630, AT3631

Country ▶ BBC231U, BC231UD: Brazil, China, Mexico, Panama
BBC300L, BC300LD, AT3630, AT3631: All countries

Description ▶ The following parts have been added as the components of the current Gear case assembly because the models are shipped without assembling nylon cutting head to shaft.

- Receive washer (331861-0: The current item No. 051.)
- Clamp washer (346084-7)
- Cup (168526-9)
- Hex nut M10-17 (264025-0)

Therefore, the part No. of Gear case assembly has been changed from 125791-3 to 125556-3.

Interchangeability(I/C)

	Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
①	037	Gear case assembly 125791-3		1	No	Gear case assembly 125556-3		1	<p>↑</p> <p>The current ①②③④⑤ are interchange- able with the new ①.</p> <p>↓</p> <p>Treat these parts as the components of new Gear case assembly 125556-3.</p> <p>↓</p>
②	051	Receive washer 331861-0		1	Yes	Receive washer 331861-0		1	
③	BBC231U, BC231UD: A15 BBC300L, BC300LD: A05	Clamp washer 346084-7		1	Yes	Clamp washer 346084-7		1	
④	BBC231U, BC231UD: A13 or A16 BBC300L, BC300LD: A03	Cup 168526-9		1	Yes	Cup 168526-9		1	
⑤	BBC231U, BC231UD: A14 BBC300L, BC300LD: A04	Hex nut M10-17 264025-0		1	Yes	Hex nut M10-17 264025-0		1	

Implementation

From October 2011 production