





# TECHNICAL INFORMATION



73404  
June, 2005

- Subject** ▶ Change of Shoulder Pin 5 and Torsion Spring 17
- For Models** ▶ BJR240, JR140D, JR180D, JR180DMD, JR3000VT, JR3030T, JR3050T
- Country** ▶ All countries
- Description** ▶ Shoulder pin 5 and Torsion spring 17 have been changed as illustrated below.

	▶ Current	▶ New
Shoulder Pin 5	 <p>(256471-1)</p>	 <p>Groove for distinction from the current (256492-3)</p>
Torsion spring 17	 <p>7.0mm (9/32") Number of turns: 4.25 (231662-5)</p>	 <p>8.5mm (11/32") Number of turns: 3.25 (231687-9)</p>

## Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
See below.	Shoulder Pin 5 256471-1		1	←	Shoulder Pin 5 256492-3		1	
See below.	Torsion Spring 17 231662-5		1	←	Torsion Spring 17 231687-9		1	

### Interchangeability mark ;

The arrow ← means that the new part can be substituted for the current.

Item number of Shoulder Pin 5

BJR240	JR140D	JR180D	JR180DMD	JR3000VT	JR3030T	JR3050T
001	083	020	081	088	006	

Item number of Torsion Spring 17

BJR240	JR140D	JR180D	JR180DMD	JR3000VT	JR3030T	JR3050T
012	094	009	092	099	015	

## Implementation

JR3050T: From May, 2005 production

The remaining models: As soon as the current parts in stock run out