

- Subject** ▶ Change on fan 90
- For Models** ▶ BO5000 and BO5000KDA (Random Orbit Sander)
- Description** ▶ The fan 90 will be changed as follows.

▶ Current (Material: Zinc alloy)	▶ New (Material: Aluminum alloy)
<p style="text-align: center;">Thickness: 2.3 mm (3/32")</p>	<p style="text-align: center;">Thickness: 3.8 mm (5/32")</p>

Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
14	Fan 90 241655-4			<=	Fan 90 241659-6			

Note


Interchangeability mark : <= mark indicates that the new type part can be substituted for the current type part.

Implementation

Model BO5000 will be replaced by Model BO5001.
 Model BO5000KDA will be replaced by Model BO5001KDA.

The current type fan 9 employed in all Models BO5000 and BO5000KDA which you sold to your customers or you have in your stock should be replaced by the new type fan 9. After replacing the fan 9, attach the following labels to tools, cartons for each tool and master cartons.

For tools



For cartons

