

**Subject** ▶ Change of Endbell Complete

**For Models** ▶ BTW150, BTW151

**Country** ▶ All countries

**Description** ▶ Endbell Complete has been changed for a quick repair as shown below.  
The new Endbell Complete can be distinguished from the current one by color of Rubber Pin.

▶ Current	▶ New
<p><b>Rubber Cap 12</b> (421790-6)</p> <p><b>Washer</b></p> <p><b>Rubber Pin (blue)</b></p> <p><b>Spacer</b></p> <p><b>Endbell Complete</b> (638088-6 / BTW150) (638073-9 / BTW151)</p> <p>Washer, Rubber Pins(4pcs.) and Spacers(4pcs.) are the constituent parts of current Endbell Complete.</p>	<p><b>Rubber Cap 12</b></p> <p><b>Washer has been eliminated.</b></p> <p><b>Rubber Pin (green)</b> It is longer by 1 mm than the current Rubber Pin (blue).</p> <p><b>No Spacer</b></p> <p><b>Endbell Complete</b> (638115-9 / BTW150) (638116-7 / BTW151)</p> <p>Rubber Pins(4pcs.) are the constituent parts of new Endbell Complete.</p>

## Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
038	Endbell Complete 638088-6		1	←	Endbell Complete 638115-9		1	For BTW150
038	Endbell Complete 638073-9		1	←	Endbell Complete 638116-7		1	For BTW151

### Interchangeability mark ;

The arrow ← means that the new part can be substituted for the current.

### Note

Washer and Spacers(4pcs.) have been eliminated in the new Endbell Complete.

### Implementation

To be informed later.