


T ECHNICAL INFORMATION



Y06286
November 2012

- Subject** ▶ Change of Part number for Band complete
- For Models** ▶ Makita: BVF154, EF1550RH, EVH2000, RBL500
DOLMAR: PB-500R, SP-1815, SP-252.4R
- Country** ▶ All countries
- Description** ▶ Plate as an integral part of Band complete has been modified.
Consequently, the part number of Band complete has been changed.



Interchangeability(I/C)

	Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
①	BVF154, SP-1815: 001 PB-500R, RBL500: A01	Band complete 6709026000		2	Yes	Band complete 6709026001		2	BVF154, PB-500R, RBL500, SP-1815
②	EF1550RH: 017 EVH2000, SP-252.4R: 018	Band complete 6909070000		2	Yes	Band complete 6909070001		2	EF1550RH, EVH2000, SP-252.4R

Implementation

- ① After the current parts in stock are cleared.
- ② Immediately upon completion of preparation. (on or after November 2012 production)