

T ECHNICAL INFORMATION




Y05935
September 2011

Subject ► Correction of Parts list

For Models ► BVF104, BVF154, SP1815

Country ► BVF104: Argentina, Austria, Brazil, Netherlands, UK,
BVF154: Argentina, Brazil, Italy, Mexico, Netherlands
SP1815: Italy, Netherlands

Description ► Parts list has been corrected as drawn below to meet the actual parts-supply.



Interchangeability(I/C)

	Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
①	BVF104: 035 BVF154, SP1815: 037	Lever compl ----- 6957029010		1	←	Lever compl ----- 6957029010		1	The part No. remains the same.

Interchangeability mark;

The arrow ← means that the new part can be substituted for the current.

Implementation

From August 2011 production