

T ECHNICAL INFORMATION





64936A
(Page 1 of 4)

- Subject** ▶ Change of Switch
- For Models** ▶ 4300V, 4300BV, 4301BV, 4301SV, 4301V, 4320, 6000LR, 6302, 6302H, 6303, 6303H, 6310, 6402, 6402X, 6403, 6405, 6406, 6510LVR, 6511LVR, 6511X, 6820V, 6800DBV, 6801DBV, 6802BV, 6805BV, 6830, 6832, 800, 8401, DA3000R, DP4700, HP1030, HP2010N, JR3000V, JR3000VT, M800, M802,
- Country** ▶ All countries
- Description** ▶ See below.



Switch has been changed as shown below.

For 4300BV, 4300V, 4301BV, 4301SV, 4301V, 4320, 6000LR, 6310, 6800DBV, 6801DBV, 800, 8401, DP4700, HP1030, M800, M802

	▶ Current	▶ New
Manufacturer	TYCO (EATON)	SATORI
Catalog No.	8653B341	TG823AB-1
Part No.	651270-0	650205-8
Shape		



Note: Its wiring and installing method remain unchanged.

For 4300BV, 4301BV, 4320, 6000LR, 6310, 6800DBV, 6801DBV, 6802BV, 6805BV, 6830, 6832, DP4700, JR3000V, JR3000VT

	▶ Current	▶ New
Manufacturer	TYCO (EATON)	SATORI
Catalog No.	8653B321	TG823TB-1
Part No.	651271-8	650206-6
Shape		



Note: Its wiring and installing method remain unchanged.

For HP1030, HP2010N

	► Current	► New
Manufacturer	TYCO (EATON)	SATORI
Catalog No.	8653B321Z	TG823TB-2
Part No.	651277-6	650207-4
Shape		



Note: Its wiring and installing method remain unchanged.

For 6302, 6303, 6402, 6402X, 6403, 6510LVR, 6511LVR, 6511X, 6820V

	► Current	► New
Manufacturer	TYCO (EATON)	SATORI
Catalog No.	8907K192	TG833TB-1
Part No.	651352-8	650208-2
Rating	6A 125V -	7A 125V -
Shape		



Note: Its wiring and installing method remain unchanged.

For 6302H, 6303H

	► Current	► New
Manufacturer	TYCO (EATON)	SATORI
Catalog No.	8907K307	TG833TB-1
Part No.	651356-0	650208-2
Rating	7A 125V -	7A 125V -
Shape		



Note: Its wiring and installing method remain unchanged.

For 6405, 6406

	► Current	► New
Manufacturer	TYCO (EATON)	SATORI
Catalog No.	8907K416	TG833TLB-1
Part No.	651927-3	650526-8
Shape		

Note: Its wiring and installing method remain unchanged.

For DA3000R

	► Current	► New
Manufacturer	TYCO (EATON)	SATORI
Catalog No.	8907K598	TG833R-1
Part No.	651982-5	650527-6
Shape		

Note: Its wiring and installing method remain unchanged.

Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
See note 1 below.	Switch 651270-0		1	Yes	Switch 650205-8		1	See note 2 below.
	Switch 651271-8		1	Yes	Switch 650206-6		1	See note 3 below.
	Switch 651277-6		1	Yes	Switch 650207-4		1	For HP1030, HP2010N
	Switch 651352-8		1	Yes	Switch 650208-2		1	See note 4 below.
	Switch 651356-0		1	Yes	Switch 650208-2		1	For 6302H, 6303H
	Switch 651927-3		1	Yes	Switch 650526-8		1	For 6405, 6406
	Switch 651982-5		1	Yes	Switch 650527-6		1	For DA3000R

Note

1. Item No. for Switch

Model	4300V	4300BV	4301BV	4301SV	4301V	4320	6000LR	6302	6302H	6303	6303H
Item No.	046	060	069	045	068	006	038	040	033	040	033

Model	6310	6402	6402X	6403	6405	6406	6510LVR	6511LVR	6511X	6800DBV
Item No.	010	039	—	039	014	014	040	—	—	036

Model	6801DBV	6802BV	6805BV	6820V	6830	6832	800	8401	DA3000R	DP4700
Item No.	036	039	054	040	048	051	016	009	030	037

Model	HP1030	HP2010N	JR3000V	JR3000VT	M800	M802
Item No.	028	037	058	076	—	028

- For 4300BV, 4301SV, 4300V, 4301BV, 4301V, 4320, 6000LR, 6310, 6800DBV, 6801DBV, 800, 8401, DP4700, HP1030, M800, M802
- For 4300BV, 4301BV, 4320, 6000LR, 6310, 6800DBV, 6801DBV, 6802BV, 6805BV, 6830, 6832, DP4700, JR3000V, JR3000VT
- For 6302, 6303, 6402, 6402X, 6403, 6510LVR, 6511LVR, 6511X, 6820V

Implementation

4300V : Discontinued since Apr., 1993
 4301BV: Discontinued since Aug., 1997
 4301SV: Discontinued since Apr., 1993
 4301V : Discontinued since Jul., 1988
 6402X : Discontinued since Feb., 2000
 800 : Discontinued since May, 2001
 8401 : Discontinued since Oct., 2000
 M800 : Discontinued since Apr., 1993
 M802 : Discontinued since Apr., 1993

All models other than the above discontinued models: To be informed later