


T ECHNICAL INFORMATION



63708A

- Subject** ▶ Change of Drill Chuck S10
- For Models** ▶ DA3000, DA3000R, DA3000V
- Country** ▶ All countries
- Description** ▶ Drill Chuck S10 has been changed as described below. To distinguish the new Drill Chuck S10 from the current one, a seven digit engraved on Chuck has been changed from "7630684" to "7631622".



Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
DA3000R: 021 DA3000V: 025 DA3000 : 025	Drill Chuck S10 763068-4		1		Drill Chuck Set 193442-6		1	Except for North American countries
DA3000R: 021 DA3000V: 025 DA3000 : 025	Drill Chuck Set 192881-7	←	1					
DA3000R: 021 DA3000V: 025 DA3000 : 025	Drill Chuck Set 763068-490A		1	←	Drill Chuck Set 193443-4		1	For North American countries

Note

Interchangeability mark ; ← means that the new part is substituted for the current.

Implementation

- DA3000: Discontinued since Apr.,1993
- DA3000R: From serial No.384265E (May,2001)
- DA3000V: From serial No.25875E (May,2001)